

Both corner pieces
before cutting



The same corner
pieces after being
cut symmetrically
with a shears



After you achieve a
desired angle of a
adjustable corner,
apply a sealing glue
to the external piece
(here you can see it
on the left), connect
both parts, press
them down and
leave (the sealant
has to solidify)

Here you can see ready adjustable corners that were cut and connected as described above

